



UTSA[®]

The University of Texas at San Antonio[™]

**Facilities & Real Estate, Construction
and Planning (RECaP) Presentation**

Presentation Topics

Thank you for sharing your valuable feedback regarding UTSA facilities, maintenance, and classroom equipment. Today's presentation will cover:

- ✓ Overview of Facilities Services
- ✓ Preventative Maintenance
- ✓ How to Submit a Service Request
- ✓ Facilities Index
- ✓ Furniture
- ✓ Classroom Upgrades



Facilities Services

- ➔ Building Maintenance & Operations
- ➔ Custodial Services
- ➔ Energy & Utility Management
- ➔ Event & Moving Services
- ➔ Grounds Maintenance
- ➔ Vehicle Maintenance



Facilities Preventive Maintenance

- ➔ The Facilities Preventive Maintenance Team completes hundreds of tasks each month
- ➔ The Team is a multi-trade group including electricians, mechanics, plumbers, etc.
- ➔ A computerized maintenance management system is used to automatically issue tasks
- ➔ Best industry practices are used to determine which equipment to PM and how often



Facilities

➔ Air Quality

- ➔ Best filtration possible in each building
- ➔ Minimum 4 air changes per hour, in alignment with [CDC recommendation](#)
- ➔ Maximum outdoor air
- ➔ Preventive maintenance regular filter changes

➔ White boards

- ➔ Portable white boards available upon request

➔ Audio/Visual

- ➔ A/V requests should be directed to [Academic Technologies](#)



Deferred Maintenance - Process

- ➔ Deferred Maintenance (DM) data is collected and vetted by Facilities trades personnel and engineers
- ➔ DM items are prioritized based on the risk of failure and potential impact to the university
- ➔ DM backlog recently reported to UT System is \$92.5M comprised of \$64.7M E&G and \$27.8M non-E&G
- ➔ DM backlog is currently \$79.2M Main Campus, \$12.5M Downtown, and \$0.8M Southwest (note: SW Campus is a work in progress)



Deferred Maintenance - Process

- ➔ Below is a sample of DM data for the category “HVAC Distribution Systems”
- ➔ Data is tagged for Category, Campus, Building, Subsystem Type, and E&G
- ➔ Each item has a priority, description, and cost estimate

Sightlines Category	Priority	Campus	Building or Site	Subsystem Type	Description / Rationale	Building GSF (or Roof SF)	E&G Auxiliary Split	Total Cost Estimate
HVAC - Distribution Systems	3	1604	NTEP	Valve	Replace Chilled Water & Condenser Water isolation valves at Chillers.	NA	E&G	\$ 100,000
HVAC - Distribution Systems	4	1604	MH	Duct Cleaning	Clean and repair high pressure duct as appropriate	180,855	E&G	\$ 300,000
HVAC - Distribution Systems	5	1604	MH	Terminal Box	Replace terminal boxes and low pressure internally-lined ducting	180,855	E&G	\$ 500,000
HVAC - Distribution Systems	6	1604	ART	Duct Cleaning	Clean and repair high pressure duct as appropriate	125,967	E&G	\$ 300,000
HVAC - Distribution Systems	7	1604	ART	Terminal Box	Replace terminal boxes and low pressure internally-lined ducting	125,967	E&G	\$ 3,200,000

Deferred Maintenance - Funding

- ➔ UTSA has requested funding to address deferred maintenance projects, which will result in significant improvements to infrastructure and an enhanced campus experience.
- ➔ Funds will be used to improve or replace infrastructure and major systems in five core buildings on the Main Campus:
 - ➔ McKinney Humanities Building
 - ➔ Flawn Sciences Building
 - ➔ Arts Building
 - ➔ John Peace Library
 - ➔ Multidisciplinary Studies Building
- ➔ Funding request for \$155M from Tuition Revenue Bonds (TRB)



Facilities Condition Index (FCI)

- In an effort to develop a validated list of Deferred Maintenance projects, RECaP solicited a Building Assessment RFP in October 2022.
- The FCI will allow the University to understand the current condition of all the buildings and associated spaces. More importantly, it will allow the development of a comprehensive prioritized renewal/repair/replacement plan.

TASK	START	END	Q1		Q2		Q3		Q4					
			Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec
PATH 1	01/09/23	11/14/23	PATH 1											
Terracon Building Assessment	01/09/23	08/31/23	Terracon Building Assessment											
Phase I - Main/Downtown	01/09/23	05/15/23	Phase I - Main/Downtown											
Phase II - ITC/PW/SW	03/01/23	06/30/23			Phase II - ITC/PW/SW									
RECaP DM List Development	05/16/23	08/31/23						RECaP DM List Development						
Final DM List	08/31/23	08/31/23											Final DM List	

Facilities Condition Index - Overview

- ➔ RECaP is conducting a comprehensive Facilities Index to assess UTSA buildings
- ➔ All five campuses included in assessment
- ➔ Buildings are divided into several groups, the oldest buildings will be assessed first
- ➔ Components that will be analyzed include exterior, roof, electrical, mechanical, plumbing, HVAC, and interior.



Facilities Condition Index - Timeline

- ➔ First building group report of building assessment ready in May of 2023
- ➔ Other groups of the building reports to follow
- ➔ All building conditions will be graded based on their conditions
- ➔ Project list to address issues will be finalized by September 1, 2023



Furniture

- ➔ RECaP team conducting inventory of common area furniture
- ➔ Common area furniture assessment will provide data for prioritization for replacement
- ➔ Working towards proactive surplussing events mid-semester to remedy influx of furniture displaced in hallways



Facilities – How to Request Service

- ➔ Facilities [iService Desk](#) – preferred method
 - ➔ All routine work requests
- ➔ Phone call to Facilities Service Center at 210-458-4262
 - ➔ Urgent and emergency situations
- ➔ Email: FacilitiesServiceCenter@utsa.edu
 - ➔ To check on a status of work request, request a change to an existing work request, or to ask for information.
- ➔ Exploring idea of QR Codes to facilitate routine work requests.



Classroom Upgrades

Summary

Total Number of Classrooms Renovated: 67
Over 40% of classrooms renovated in last two years

Total Cost: \$31,731,568

- Pilot: \$3,147,265
- Phase I: \$6,284,303
- Phase II: \$22,300,000

Total Classrooms:

- Pilot: 11 classrooms (including 5 OLEs)
- Phase I: 17 classrooms
- Phase II: 39 classrooms



Current Classroom Renovations

Classroom Prioritization Criteria

Bldg.	Room #	Seating Capacity	1 Furniture	2 Walls	3 Flooring	4 Lights	5 Electric Power	6 AV Equipment	7 WiFi Equipment	8 Wired Infrastructure	9 SUE Score <i>inverse</i>	10 Locatio Priority <i>inverse</i>	11 Overall Score <i>Ave 1-10</i>	Persona
AET	0.102	30	4	2	3	4	4	1.5	4	4	2.5	5	3.4	unclassroom
ARTS	2.03.18A	48	3	3	2	3	1	1.75	4	3	0	0	2.1	Connected
DB	2.210	32	2	2	3	4	1	1.5	5	3	1.875	1	2.4	Active Connected
EB	2.04.02	47	3	2	2	4	4	1.5	5	1	1.25	0	2.4	Connected
FLN	2.02.10	119	1	5	2	3	1	1.75	5	3	0.625	0	2.2	Connected
FS	1.522	26	2	3	2	3	1	1.5	5	1	2.5	0	2.1	Active Connected
MB	1.124	48	3	2	3	4	1	1.5	3	4	0.625	0	2.2	unclassroom
MB	0.106	245	4	3	3	3	1	3	5	4	1.25	0	2.7	Connected
MB	0.104	456	4	3	3	4	1	3.25	5	4	3.125	0	3.0	Connected
MH	3.04.06	48	1	2	2	3	1	1.5	3	3	1.25	1	1.9	Active Connected

- ➔ Architectural
- ➔ MEP Infrastructure
- ➔ IT Infrastructure


- ➔ Classroom SUE Score
- ➔ AV Infrastructure
- ➔ AV Persona Opportunity

Current Classroom Renovations

Main Campus

- North Paseo
 - 6 → 5 (*converted 2 classrooms to 1*)
- McKinney
 - 12 classrooms
- Business
 - 4 *classrooms*
- Multidisciplinary
 - 5 classrooms
- Main
 - 4 *classrooms*
- Flawn
 - 6 *classrooms*
- Engineering
 - 2 classrooms
- Arts
 - 2 classrooms
- AET
 - 1 classrooms
- SEB
 - 2 classrooms

Classrooms Updated




Current Classroom Renovations

Downtown Campus

Renovated Classrooms

- Durango
 - 3 classrooms
- Frio
 - 2 classrooms
- Buena Vista
 - 1 classroom

Classrooms Updated



Questions?